

color**VIBE**

dtf

100% cotton, 100% polyester, sublimated polyester, cotton/poly blends, triblend, mesh, canvas, nylon, and more

STEP 1 **PREP**

Proof your order before application to sellable garments. Test print one of the provided extra transfers. To conduct multiple tests, cut the extra transfer into 2 or 4 pieces.

Pre-heat garment 3-5 seconds to remove any excess moisture.

STEP 2 **APPLY**



TEMPERATURE

275-300°F



DWELL TIME

10-12 seconds



PRESSURE

firm (45-65 psi)



PEEL

hot

Having trouble peeling hot?

Try a delayed hot peel or a cold peel.

TIPS & **TECHNIQUES**

FLAT SURFACE

Avoid obstructions such as zippers, seams, or buttons which will cause inconsistent pressure.

WASH INSTRUCTIONS

Machine wash garment inside out using warm water and mild detergent. Do not bleach. Do not iron on decoration.

SHELF LIFE

When properly stored, this product is guaranteed up to six months from the date of production.



**RE-PRESS COVERED WITH PARCHMENT OR SILICONE
PAPER FOR AN ADDITIONAL 5 SECONDS**



color**VIBE** *hybrid*

100% cotton, 100% polyester, sublimated polyester, cotton/poly blends, triblends, mesh, canvas, nylon, and more

STEP 1 **PREP**

Proof your order before application to sellable garments. Test print one of the provided extra transfers. To conduct multiple tests, cut the extra transfer into 2 or 4 pieces.

Pre-heat garment 3-5 seconds to remove any excess moisture.

STEP 2 **APPLY**



TEMPERATURE

275°F (nylon, heat sensitive)
300°F (cotton, poly, blends)



DWELL TIME

10-12 seconds



PRESSURE

firm (45-65 psi)



PEEL

hot (cotton, poly, blends)
cold (nylon, heat sensitive)

TIPS & TECHNIQUES

FLAT SURFACE

Avoid obstructions such as zippers, seams, or buttons which will cause inconsistent pressure.

WASH INSTRUCTIONS

Machine wash garment inside out using warm water and mild detergent. Do not bleach. Do not iron on decoration.

SHELF LIFE

When properly stored, this product is guaranteed up to six months from the date of production.



**RE-PRESS COVERED WITH PARCHMENT OR SILICONE
PAPER FOR AN ADDITIONAL 5 SECONDS**



HOWARD MULTI-PURPOSE

STANDARD APPLICATION

100% cotton, cotton/poly blends

STEP 1

PREP

Proof your order before application to sellable garments. Test print one of the provided extra transfers. To conduct multiple tests, cut the extra transfer into 2 or 4 pieces.

Pre-heat garment 3-5 seconds to remove any excess moisture.

STEP 2

APPLY



TEMPERATURE

350°F



DWELL TIME

10-12 seconds



PRESSURE

medium (32-38 psi)



PEEL

hot, immediately

TIPS &

TECHNIQUES

FLAT SURFACE

Avoid obstructions such as zippers, seams, or buttons which will cause inconsistent pressure.

WASH INSTRUCTIONS

Machine wash garment inside out using warm water and mild detergent. Do not bleach. Do not iron on decoration.

SHELF LIFE

When properly stored, this product is guaranteed up to six months from the date of production.



HOWARD MULTI-PURPOSE

LOW-TEMPERATURE APPLICATION

100% polyester, mesh, Lycra, spandex, knit rayon, triblend

STEP 1 PREP

Proof your order before application to sellable garments. Test print one of the provided extra transfers. To conduct multiple tests, cut the extra transfer into 2 or 4 pieces.

Pre-heat garment 3-5 seconds to remove any excess moisture.

STEP 2 APPLY



TEMPERATURE

310°F



DWELL TIME

15-20 seconds



PRESSURE

medium (32-38 psi)



PEEL

hot, immediately

TIPS & TECHNIQUES

FLAT SURFACE

Avoid obstructions such as zippers, seams, or buttons which will cause inconsistent pressure.

WASH INSTRUCTIONS

Machine wash garment inside out using warm water and mild detergent. Do not bleach. Do not iron on decoration.

SHELF LIFE

When properly stored, this product is guaranteed up to six months from the date of production.



PUFF [2.0]

100% cotton, cotton/poly blends

STEP 1 PREP

Proof your order before application to sellable garments. Test print one of the provided extra transfers. To conduct multiple tests, cut the extra transfer into 2 or 4 pieces.

Pre-heat garment 3-5 seconds to remove any excess moisture.

STEP 2 APPLY



TEMPERATURE

320°F



DWELL TIME

8-10 seconds



PRESSURE

medium



PEEL

hot

TIPS & TECHNIQUES

FLAT SURFACE

Avoid obstructions such as zippers, seams, or buttons which will cause inconsistent pressure.

WASH INSTRUCTIONS

Machine wash garment inside out using warm water and mild detergent. Do not bleach. Do not iron on decoration.

SHELF LIFE

When properly stored, this product is guaranteed up to six months from the date of production.



ULTRA STRETCH

100% polyester, spandex, compression gear, moisture wicking

STEP 1 PREP

Proof your order before application to sellable garments. Test print one of the provided extra transfers. To conduct multiple tests, cut the extra transfer into 2 or 4 pieces.

Pre-heat garment 3-5 seconds to remove any excess moisture.

STEP 2 APPLY



TEMPERATURE
335-340°F



DWELL TIME
12-14 seconds



PRESSURE
medium (32-38 psi)



PEEL
cold

TIPS & TECHNIQUES

FLAT SURFACE

Avoid obstructions such as zippers, seams, or buttons which will cause inconsistent pressure.

WASH INSTRUCTIONS

Machine wash garment inside out using warm water and mild detergent. Do not bleach. Do not iron on decoration.

SHELF LIFE

When properly stored, this product is guaranteed up to six months from the date of production.



GLITTER

100% cotton, cotton/poly blends

STEP 1 PREP

Proof your order before application to sellable garments. Test print one of the provided extra transfers. To conduct multiple tests, cut the extra transfer into 2 or 4 pieces.

Pre-heat garment 3-5 seconds to remove any excess moisture.

STEP 2 APPLY



TEMPERATURE
350°F



DWELL TIME
10-12 seconds



PRESSURE
firm (40+ psi)



PEEL
hot, immediately

TIPS & TECHNIQUES

FLAT SURFACE

Avoid obstructions such as zippers, seams, or buttons which will cause inconsistent pressure.

WASH INSTRUCTIONS

Machine wash garment inside out using warm water and mild detergent. Do not bleach. Do not iron on decoration.

SHELF LIFE

When properly stored, this product is guaranteed up to six months from the date of production.



HOWARD HOT PEEL

100% cotton, cotton/poly blends

STEP 1 PREP

Proof your order before application to sellable garments. Test print one of the provided extra transfers. To conduct multiple tests, cut the extra transfer into 2 or 4 pieces.

Pre-heat garment 3-5 seconds to remove any excess moisture.

STEP 2 APPLY



TEMPERATURE
375-385°F



DWELL TIME
10-12 seconds



PRESSURE
firm (40+ psi)



PEEL
hot, immediately

TIPS & TECHNIQUES

FLAT SURFACE

Avoid obstructions such as zippers, seams, or buttons which will cause inconsistent pressure.

WASH INSTRUCTIONS

Machine wash garment inside out using warm water and mild detergent. Do not bleach. Do not iron on decoration.

SHELF LIFE

When properly stored, this product is guaranteed up to six months from the date of production.



VINTAGE WASH MP

100% cotton, cotton/poly blends, triblend, canvas, knit rayon

STEP 1 PREP

Proof your order before application to sellable garments. Test print one of the provided extra transfers. To conduct multiple tests, cut the extra transfer into 2 or 4 pieces.

Pre-heat garment 3-5 seconds to remove any excess moisture.

STEP 2 APPLY



TEMPERATURE
350°F



DWELL TIME
10-12 seconds



PRESSURE
firm (40+ psi)



PEEL
hot, immediately

TIPS & TECHNIQUES

FLAT SURFACE

Avoid obstructions such as zippers, seams, or buttons which will cause inconsistent pressure.

WASH INSTRUCTIONS

Machine wash garment inside out using warm water and mild detergent. Do not bleach. Do not iron on decoration.

SHELF LIFE

When properly stored, this product is guaranteed up to six months from the date of production.



VINTAGE WASH HHP

100% cotton, cotton/poly blends

STEP 1 PREP

Proof your order before application to sellable garments. Test print one of the provided extra transfers. To conduct multiple tests, cut the extra transfer into 2 or 4 pieces.

Pre-heat garment 3-5 seconds to remove any excess moisture.

STEP 2 APPLY



TEMPERATURE
375-385°F



DWELL TIME
10-12 seconds



PRESSURE
firm (40+ psi)



PEEL
hot, immediately

TIPS & TECHNIQUES

FLAT SURFACE

Avoid obstructions such as zippers, seams, or buttons which will cause inconsistent pressure.

WASH INSTRUCTIONS

Machine wash garment inside out using warm water and mild detergent. Do not bleach. Do not iron on decoration.

SHELF LIFE

When properly stored, this product is guaranteed up to six months from the date of production.



GLOW IN THE DARK

100% cotton, 100% polyester, cotton/poly blends, mesh, canvas, triblends

STEP 1 PREP

Proof your order before application to sellable garments. Test print one of the provided extra transfers. To conduct multiple tests, cut the extra transfer into 2 or 4 pieces.

Pre-heat garment 3-5 seconds to remove any excess moisture.

STEP 2 APPLY



TEMPERATURE

350°F or 310°F



DWELL TIME

10-12 or 15-20 seconds



PRESSURE

medium (32-38 psi)



PEEL

hot, immediately

TIPS & TECHNIQUES

FLAT SURFACE

Avoid obstructions such as zippers, seams, or buttons which will cause inconsistent pressure.

WASH INSTRUCTIONS

Machine wash garment inside out using warm water and mild detergent. Do not bleach. Do not iron on decoration.

SHELF LIFE

When properly stored, this product is guaranteed up to six months from the date of production.



REVOLUTION

100% cotton, 100% polyester, cotton/poly blends, nylon, mesh, acrylic, spandex, some waterproof materials

STEP 1 PREP

Proof your order before application to sellable garments.

Pre-heat garment 3-5 seconds to remove any excess moisture.

STEP 2 APPLY



TEMPERATURE
285°F



DWELL TIME
6 seconds (20 for nylon)



PRESSURE
medium (32-38 psi)



PEEL
hot or cold (nylon only)

TIPS & TECHNIQUES

FLAT SURFACE

Avoid obstructions such as zippers, seams, or buttons which will cause inconsistent pressure.

WASH INSTRUCTIONS

Machine wash garment inside out using warm water and mild detergent. Do not bleach. Do not iron on decoration.

SHELF LIFE

When properly stored, this product is guaranteed up to six months from the date of production.



BLING

100% cotton, cotton/poly blends

STEP 1 PREP

Proof your order before application to sellable garments.

Pre-heat garment 3-5 seconds to remove any excess moisture.

STEP 2 APPLY



TEMPERATURE
330°F



DWELL TIME
15 seconds



PRESSURE
medium (32-38 psi)



PEEL
cold

TIPS & TECHNIQUES

FLAT SURFACE

Avoid obstructions such as zippers, seams, or buttons which will cause inconsistent pressure.

WASH INSTRUCTIONS

Machine wash garment inside out using warm water and mild detergent. Do not bleach. Do not iron on decoration.

SHELF LIFE

When properly stored, this product is guaranteed up to six months from the date of production.



3M REFLECTIVE

100% cotton, 100% polyester, cotton/poly blends, nylon, mesh, acrylic, spandex, some waterproof materials

STEP 1 PREP

Proof your order before application to sellable garments.

Pre-heat garment 3-5 seconds to remove any excess moisture.

STEP 2 APPLY



TEMPERATURE
305°F



DWELL TIME
15 seconds



PRESSURE
firm (40+ psi)



PEEL
cold

TIPS & TECHNIQUES

FLAT SURFACE

Avoid obstructions such as zippers, seams, or buttons which will cause inconsistent pressure.

WASH INSTRUCTIONS

Machine wash garment inside out using warm water and mild detergent. Do not bleach. Do not iron on decoration.

SHELF LIFE

When properly stored, this product is guaranteed up to six months from the date of production.



PRINT & CUT

LOW-TEMP APPLICATION

100% cotton, 100% polyester, cotton/poly blends, mesh, some waterproof materials

STEP 1

PREP

Proof your order before application to sellable garments.

Pre-heat garment 3-5 seconds to remove any excess moisture.

STEP 2

APPLY



TEMPERATURE

245°F



DWELL TIME

20 seconds



PRESSURE

medium-firm (32-40+ psi)



PEEL

hot

TIPS &

TECHNIQUES

FLAT SURFACE

Avoid obstructions such as zippers, seams, or buttons which will cause inconsistent pressure.

WASH INSTRUCTIONS

Machine wash garment inside out using warm water and mild detergent. Do not bleach. Do not iron on decoration.

SHELF LIFE

When properly stored, this product is guaranteed up to six months from the date of production.



PRINT & CUT

NYLON APPLICATION

nylon, acrylic

STEP 1 PREP

Proof your order before application to sellable garments.

Pre-heat garment 3-5 seconds to remove any excess moisture.

STEP 2 APPLY



TEMPERATURE

285°F



DWELL TIME

5 seconds, peel
+15 seconds covered



PRESSURE

medium-firm (32-40+ psi)



PEEL

cold

TIPS & TECHNIQUES

FLAT SURFACE

Avoid obstructions such as zippers, seams, or buttons which will cause inconsistent pressure.

WASH INSTRUCTIONS

Machine wash garment inside out using warm water and mild detergent. Do not bleach. Do not iron on decoration.

SHELF LIFE

When properly stored, this product is guaranteed up to six months from the date of production.

